Compliance File

EVENT VIOLATIONS INSPECTORS STATEMENT

			EVENT VIOLATIONS IN THE STATE OF THE STATE O
	Compa Permit	ny/Mine # <u></u>	Lodestar Energy Horizon Mine NOVICO # CO2-46-1-1 Violation # 1 of 1
	Α.	,	ISNESS Cessation Order (to cease discharge of the dirty water
		1.	What type of event is applicable to the regulation cited? Refer to the GOGM reference list of events below and remember that the event is NOT the same as the violation. Mark and explain each event.
		XCCXXCCC	 a. Activity outside the approved permit area. b. Injury to the public (public safety). c. Damage to property. d. Conducting activities without appropriate approvals. e. Environmental harm. f. Water pollution. g. Loss of reclamation/revegetation potential. h. Reduced establishment, diverse and effective vegetative cover. l. No event occurred as a result of the violation. j. Other.
	Explan	ation: 1	Dirty mine water was observed discharging from the
0 SL B	Hori n 3 ample the	\$15/ perm	Dirty mine water was observed discharging from the Dirty mine water was observed discharging from the Mine undisturbed by pass culvert into Jewkes Creek 2002 at approximately 10 30 pm. After taking a grab e inspector decided to issue a verbal ressolution thee to cease all pumping to the outside. Has the event occurred? Yes No_
		,	Yes: Describe it.
			No: What would cause it to occur and what is the probability of the event(s) occurring? (None, Unlikely, Likely).
	•	nation:	> To document the verbal CO, a written CO
	wa	us pr	repared on 3/18/2002, Same was forwarded permittee, and the Division, SLO.
	to	the	permittee, and the Division, SLO,
		3.	Did any damage occur as a result of the violation?
			No.
			Yes: Describe the duration and extent of the damage or impact. How much damage may have occurred if the violation had not been discovered by a DOGM inspector? Describe this potential damage and whether or not it would extend off the disturbed and/or permit area.
	Explai	nation:	Mine sludge and coal times are visible on
	the.	edges	s of flow path in Jewkes Creek both mount
6	and	out	not it would extend off the disturbed and/or permit area. Mine sludge and coal flines are visible on sof flow path in Jewher Creek both inside side of the permit boundary. Dwk has reported 1 3/22/02, no evidence of a fish kill exists. Revised 1/98
Ł	bat :	as of	1 3/22/02, no evidense of a Just series 1/98

Page 2 Inspector Statement Event Violations

-NOV/CO # <u>02 - 46 - 1 - 1</u> Violation # <u>1</u> of <u>1</u>

- B. <u>DEGREE OF FAULT</u> (Check the statements which apply to the violation and discuss.)
 - () Was the violation not the fault of the operator (due to vandalism or an act of God), explain. Remember that the permittee is considered responsible for the actions of all persons working on the mine site.

Explanation:

Was the violation the result of not knowing about DOGM regulations, indifference to DOGM regulations or the result of lack of reasonable care.	
Explanation: The violation) occurred because the permittee's management does not understand the implications and	
regulrements of a UPDES permit. Dirty water was discharged because mine management tell that pumping different the section to outside would improve conditions to	rectly!
from the section to outside would improve conditions to the public should have been evident to a careful operator, describe the situation and what, if anything, the operator did to correct it prior to being cited.	

Lodestar corporate to show a profit or be shot down.

Was the operator in violation of a specific permit condition?

Explanation: Yes. The water exceeded the maximum daily allowable limit for total suspended solids (70mg/L) by 286 mg/L, per UPDES permit # UT6040000.

() Has DOGM or OSM cited the violation in the past? If so, give the dates and the type of warning or enforcement action taken.

Explanation:

C. **GOOD FAITH**

In order to receive good faith for compliance with an NOV or CO, the violation must have been abated before the abatement deadline. If you think this applies, describe how rapid compliance was achieved (give dates) and describe the measures the

operator took to comply as rapidly as possible. Upon issuance of the verbal cessation order, Horrson management immediately took action to re-plumb the in-Mine pump system to redirect the section flow though the in-Mine sump, such that the suspended solids through the in-Mine sump, such that the suspended solids would settle out prior to the water discharging outExplain whether or not the operator had the necessary resources on site to achieve of side compliance.

The operator had all the necessary resources at the site to correct the plumbing problem. It took less than 30 minutes to correct the problem.

Was the submission of plans prior to physical activity required by this NOV/CO? Yes__ No_X If yes, explain.